

Prüfinstitut für Abwassertechnik GmbH

*Prüfeinrichtung des Prüf- und Entwicklungsinstituts
für Abwassertechnik an der RWTH Aachen*

PIA

Prüfinstitut für
Abwassertechnik
GmbH



DIN EN ISO 9001:2000

**Report on the treatment efficiency test
according to EN 12566-3 of the small
wastewater treatment plant**

BusseMF-HKA 4 P plus

by

Busse Innovative Systeme GmbH

Test report – No PIA2009-100B60P

Aachen, June 2009

A handwritten signature in blue ink, appearing to read 'Elmar Lancé'.

Dipl.-Ing. Elmar Lancé

PIA GmbH
Prüfinstitut für Abwassertechnik
Hergenrather Weg
52074 Aachen



TABLE OF CONTENTS

1 INTRODUCTION.....	3
2 DESCRIPTION OF THE SMALL WASTEWATER TREATMENT PLANT BUSSEMF-HKA 4 P PLUS.....	4
2.1 DESCRIPTION OF THE TANK	5
2.2 DESCRIPTION OF THE TREATMENT PROCESS	6
2.3 WATERTIGHTNESS TEST.....	9
3 SAMPLING AND ANALYSIS.....	10
4 COURSE AND PARTICULARITIES OF THE EXAMINATION.....	11
5 TREATMENT EFFICIENCY	13
5.1 INDIVIDUAL RESULTS.....	13
5.2 EVALUATION OF THE TEST SEQUENCES	20
5.3 GRAPHICAL PRESENTATION.....	23
6 ASSESSMENT OF THE OPERATIONAL SAFETY.....	30
6.1 OPERATIONAL RELIABILITY OF THE SYSTEM	30
6.2 SLUDGE LEVEL MEASUREMENT AND SLUDGE REMOVAL	30
6.3 MAINTENANCE AND SELF MONITORING	31
6.4 ACCESSIBILITY	31
7 ANNEX	31

